



Warranty Claim Form

Claim details

Claim reference:	MP150
Claim type:	Pre-service Engine Parts please circle one
Customer name:	AC Automation
Technician:	Paul Hutchinson
Technician email:	paul@marapco.com
Technician phone:	077123123456
Branch:	Marapco

Travel & labour

Engine location:	Carrickfergus
Travel distance:	5 miles
Travel time:	10 mins
Engine removed?	No
If yes, engine removal time:	0 mins
Total repair time:	30 mins

Engine details

Engine serial number:	PP82576U563223E
In service date:	25/4/18
Failure date:	23/4/19
Repair date:	25/4/19
Running hours:	30 hours
Description of failure and work carried out:	Engine oil pressure was not reading correctly on the DSE controller, checked the wiring and DSE controller. Found the problem was with the Perkins oil pressure sender, replaced and retested successfully.
No. of images attached:	2

Failure details

Failed part number:	2848A071
Failed part description:	Oil Pressure Sender
Failure code:	Inoperative
New part number:	2848A071
Price:	£ 25
Quantity:	1
Total parts cost:	£ 25

Once complete, please email form to warranty@marapco.com

